

## CAUTION

SERIES RATED SYSTEM COMBINATION RATED 22  
KAIC. (PANEL EMDP, TYPE DK MAIN BREAKER  
WITH TYPE BAB BRANCH BREAKERS.) IDENTIFIED  
REPLACEMENT COMPONENTS REQUIRED. SEE  
BSU ENGINEERING FOR DETAILS.

BALL STATE UNIVERSITY – JUNE 22, 2016

## CAUTION

SERIES RATED SYSTEM COMBINATION RATED 18  
KAIC. (PANEL RP-3A, TYPE EHD MAIN BREAKER  
WITH TYPE BAB BRANCH BREAKERS.) IDENTIFIED  
REPLACEMENT COMPONENTS REQUIRED. SEE  
BSU ENGINEERING FOR DETAILS.

BALL STATE UNIVERSITY – JUNE 22, 2016

## CAUTION

SERIES RATED SYSTEM COMBINATION RATED 18  
KAIC. (PANEL RP-3B, TYPE EHD MAIN BREAKER  
WITH TYPE BAB BRANCH BREAKERS.) IDENTIFIED  
REPLACEMENT COMPONENTS REQUIRED. SEE  
BSU ENGINEERING FOR DETAILS.

BALL STATE UNIVERSITY – JUNE 22, 2016

## CAUTION

SERIES RATED SYSTEM COMBINATION RATED 65  
KAIC. (PANEL RP-BA, TYPE ED MAIN BREAKER  
WITH TYPE BAB BRANCH BREAKERS.) IDENTIFIED  
REPLACEMENT COMPONENTS REQUIRED. SEE  
BSU ENGINEERING FOR DETAILS.

BALL STATE UNIVERSITY – JUNE 22, 2016